

# Statistical quality control



## Overview

A **control chart** monitors a process over time by plotting a summary statistic from successive samples against the sample number. Two horizontal lines — the **upper control limit (UCL)** and **lower control limit (LCL)** — bound the region of expected variation. Points outside these limits signal a possible **special cause**.

Quality characteristic	Chart type	Charts used
Continuous variable	Variables control chart	$\bar{X}$ chart, $R$ chart, $S$ chart
Binary (defective/not)	Attribute control chart	$p$ chart
Count of defects	Attribute control chart	$c$ chart

**Key notation:**  $k$  = number of samples (subgroups);  $n$  = subgroup size (items per sample).

**Note:** Always construct the **variation chart** ( $R$  or  $S$ ) before the mean chart ( $\bar{X}$ ). The centerline of the variation chart is needed to compute the  $\bar{X}$  chart limits.

## The $R$ chart (sample range)

The  $R$  chart monitors process variability using the range of each subgroup.

$$\bar{R} = \frac{1}{k} \sum_{i=1}^k R_i \quad \text{UCL} = D_4 \bar{R} \quad \text{LCL} = D_3 \bar{R}$$

Constants  $D_3$  and  $D_4$  depend on subgroup size  $n$  (from control chart constants table). The process standard deviation can be estimated as  $\hat{\sigma} = \bar{R}/d_2$ .

## The $S$ chart (sample standard deviation)

The  $S$  chart is an alternative to the  $R$  chart, also used to monitor process variability. It uses the standard deviation of each subgroup rather than the range. For large  $n$ , it is more precise than the  $R$  chart.

$$\bar{s} = \frac{1}{k} \sum_{i=1}^k s_i \quad \text{UCL} = B_4 \bar{s} \quad \text{LCL} = B_3 \bar{s}$$

Constants  $B_3$  and  $B_4$  depend on  $n$  (from table). The process standard deviation can be estimated as  $\hat{\sigma} = \bar{s}/c_4$ .

## The $\bar{X}$ chart (sample mean)

Once the  $R$  or  $S$  chart is in control, the  $\bar{X}$  chart monitors the process mean.

**Using  $R$ :**

$$\bar{\bar{x}} = \frac{1}{k} \sum_{i=1}^k \bar{x}_i \quad \text{UCL} = \bar{\bar{x}} + A_2 \bar{R} \quad \text{LCL} = \bar{\bar{x}} - A_2 \bar{R}$$

**Using  $S$ :**

$$\text{UCL} = \bar{\bar{x}} + A_3 \bar{s} \quad \text{LCL} = \bar{\bar{x}} - A_3 \bar{s}$$

Constants  $A_2$  and  $A_3$  depend on  $n$  (from table).

## Workflow for variables control charts

1. Choose rational subgroups (variation within each subgroup should reflect only common causes).
2. Compute the  $R$  or  $S$  chart. Identify and investigate any out-of-control points.
3. Remove samples associated with out-of-control points and recompute the  $R$  or  $S$  chart.
4. Once the variation chart is in control, compute the  $\bar{X}$  chart (omitting the same removed samples).
5. If the  $\bar{X}$  chart shows out-of-control points, identify and correct the special causes.
6. Continue monitoring both charts.

## Average run length (ARL)

A **false alarm** occurs when a point plots outside the control limits even though the process is in control. A **failure to detect** occurs when the process is out of control but no point plots outside the limits.

The **average run length** is the expected number of samples observed before a point plots outside the control limits:

$$\text{ARL} = \frac{1}{p}$$

where  $p$  is the probability that any given point plots outside the control limits.

**Example:** A process has  $\mu = 3$ ,  $\sigma = 1$ , and samples of size  $n = 4$ . A special cause shifts the mean to  $\mu = 3.5$ . Find the ARL.

**Solution:** The  $\bar{X}$  chart has 3-sigma limits based on  $\sigma_{\bar{x}} = \sigma/\sqrt{n} = 1/2 = 0.5$ :

$$\text{UCL} = 3 + 3(0.5) = 4.5 \quad \text{LCL} = 3 - 3(0.5) = 1.5$$

After the shift,  $\bar{X} \sim N(3.5, 0.5^2)$ . The probability of a point falling outside the limits:

$$p = P(\bar{X} > 4.5) + P(\bar{X} < 1.5) = P\left(Z > \frac{4.5 - 3.5}{0.5}\right) + P\left(Z < \frac{1.5 - 3.5}{0.5}\right) = P(Z > 2) + P(Z < -4)$$

$$p \approx 0.0228 + 0 = 0.0228 \quad \text{ARL} = \frac{1}{0.0228} \approx 43.9 \text{ samples}$$

## The $p$ chart (proportion defective)

Used when each unit is classified as **defective or not** (binary). Let  $\hat{p}_i = x_i/n$  be the proportion defective in sample  $i$ .

$$\bar{p} = \frac{1}{k} \sum_{i=1}^k \hat{p}_i \quad \text{UCL} = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}} \quad \text{LCL} = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

**Note:** If the computed LCL is negative, set LCL = 0.

**Interpreting out-of-control points on a  $p$  chart:**

- Point **above the UCL**: the proportion of defectives has increased. Identify and **remove** the special cause.
- Point **below the LCL**: the proportion of defectives has decreased. Identify the special cause and **make it permanent** to sustain the improvement.

## The $c$ chart (count of defects)

Used when the quality measurement is a **count of defects** in a unit. Requires that defects follow a **Poisson distribution**. Let  $c_i$  be the number of defects in unit  $i$  and  $\bar{c}$  be the average.

$$\bar{c} = \frac{1}{k} \sum_{i=1}^k c_i \quad \text{UCL} = \bar{c} + 3\sqrt{\bar{c}} \quad \text{LCL} = \bar{c} - 3\sqrt{\bar{c}}$$

**Note:** If the computed LCL is negative, set LCL = 0. The same interpretation of above/below the control limits applies as with the  $p$  chart.

## Summary of control chart formulas

Chart	Centerline	UCL	LCL
$R$	$\bar{R}$	$D_4\bar{R}$	$D_3\bar{R}$
$S$	$\bar{s}$	$B_4\bar{s}$	$B_3\bar{s}$
$\bar{X}$ (using $R$ )	$\bar{\bar{x}}$	$\bar{\bar{x}} + A_2\bar{R}$	$\bar{\bar{x}} - A_2\bar{R}$
$\bar{X}$ (using $S$ )	$\bar{\bar{x}}$	$\bar{\bar{x}} + A_3\bar{s}$	$\bar{\bar{x}} - A_3\bar{s}$
$p$	$\bar{p}$	$\bar{p} + 3\sqrt{\bar{p}(1-\bar{p})/n}$	$\bar{p} - 3\sqrt{\bar{p}(1-\bar{p})/n}$
$c$	$\bar{c}$	$\bar{c} + 3\sqrt{\bar{c}}$	$\bar{c} - 3\sqrt{\bar{c}}$